

Graco Line Painter Winterization — Jerry

- **Per Phone Call to Graco Tech Service 11/13/2025**
 - Fully charge Batteries before storing
 - Protect batteries from freezing, 30°F degrees min (Lowest recorded temperature in building last Winter was 5°F)
 - To remove batteries:
 - Remove Paint Buckets
 - Remove “No Step” cover plate
 - Remove four battery terminal connections
 - Remove batteries and store in a warm room
 - Battery replacement cost is \$4k total for the two large Lithium batteries that power the paint pumps, solenoids, instruments and controls.
-
- Prepare Paint Circuit For Storage
 - Completely fill machine with Pump Armor or Pink RV Antifreeze